

## EGOLF AGREEMENT 021-2016

Subject of Agreement	<b>Interpretation of definitions</b>
Related test standard	TS 1187 TM2 and EN 13501-5
Date of issue	2013-03-13
Reference original query	TC1, N499, Helpdesk 2012-13
Previous publication number (if applicable)	EGR 73
Keywords (max. 20)	interpretation, definition, roof, damaged

### Problem

This question concerns the interpretation of following definitions in the TS 1187-test 2 and EN 13501-5.

Damaged length:

Length of damaged material of the roof covering and the substrate respectively, expressed in mm as measured from the centre of the wood crib position (for test 2)

Question: is the length of damaged material measured in the upwards direction or in the upwards and downwards direction

### Agreement

Length of damaged material of the roof covering and the substrate respectively, expressed in mm, is measured in the upwards direction from the centre of the wood crib position (TM2).